



**POCKET
DIGITAL
THERMOMETER**

To measure temperature with this unit follow these simple instructions:

Select either the Fahrenheit or Celsius mode:

- With the unit "off" press and continue to hold the ON/OFF button. The LCD will alternate between °F and °C.
- Release the ON/OFF button when desired measurement mode appears on the LCD.

Remove the protective sheath from the stem.

Press the ON/OFF button.

Insert stem into area or object to be tested. At least 1/2" of the stem must be inserted.

WARNING: The stem is a sharp and pointed object which can be dangerous.

The Data Hold function is used by pressing the D-H button when taking a measurement. The measurement will flash on the LCD when Data Hold is in use. To return to normal function, press and release the D-H button a second time.

Press the ON/OFF button to end operation, or the unit will automatically power off after 35 minutes.

Combustion Control Ltd.

Specifications:

Range	-58° to 300°F/-50° to 150°C
Resolution	0.1°F/°C
Accuracy	±2°F/±1°C
Sampling Time	1.5 seconds
Battery	1.5 Volt Button

THIS INSTRUMENT is in compliance with EN 50 081-1:1992, EN 50 082-1:1992, IEC 801-2:1984, IEC 801-3:1984, IEC 801-4:1988

**Test Products
International, Inc.
Beaverton, OR 97005**
503-520-9197 Fax: 503-520-1225
www.testproductsintl.com
email: sales@testproductsintl.com

MADE IN KOREA



6 37623 00312 7